Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/12012NW4053/1

Work Order Type: Weatherization

Audit Name: Audit-12012NW4053

CLIENT INFORMATION

Client Name: 12012NW4053 Address:

38242 Client ID: 12012NW4053

Alt. Client ID: Henry

CLIENT CONTACT INFORMATION

12012NW4053 Applicant/Person of **V**

Record

AGENCY INFORMATION

Agency: Northwest TN EDC Agency Phone: (731) 364-3228

Address: 231 S. Wilson Street Fax:

> Dresden, TN 38225 **Email Address:**

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Contractor to follow the Southeast Field Guide as applicable.

Client Name: 12012NW4053 Client ID: 12012NW4053 Alt. Client ID: Henry

Work Order (Bid Form)

DOE Weatherization Assistant Work Order Name: WO/12012NW4053/1 Version 8.6.0 Report Run On: 5/24/2010 Page 1 of 4

Measures

	Measure 1		stribute Existing Vapo	or Barrier i	n	Component	ts		ı	nspected
C	omment									
						Estimated			Actual	
#	Material / Lab	or	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Labor		•		1					
2	Miscellaneou	ıs Su			1					
(Other Detail									
					Measur	e Sub Total:] ;	Sub Total:	
ſ	Field Notes:					<u> </u>				
	comment -Ail -Ail -Ail	r seal r seal r seal	eral Air Sealing around all windows trim around all doors with clear caulk top and (approx. 213 ft)	d bottom of		_	perimete	er walls		Inspected
						Estimated	Actual			
#	Material / Lab	or	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation		General air sealing (setup cost)	Each	1					
10	Miscellaneou	ıs Su	Infiltration Reduction	Each	1					
C	Other Detail									
					Measur	e Sub Total:] ;	Sub Total:	
	Field Notes:									

Report Run On: 5/24/2010

Measure 3 Clean Blower and Coils (Evaporator and Condenser)			Component	ts	Inspected			
Comment								
			Estimated	<u> </u>	Actual			
# Material / Labor Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Labor		1						
2 Heating Equipmen		1						
Other Detail	_							
		Measur	e Sub Total:			Sub Total:		
Measure 4 CO Monitor is Needed Comment			Component				Inspected	
Comment			Estimated			Actual	Inspected	
Comment # Material / Labor Description / Comment		Qty	-		Qty		Inspected	
Comment # Material / Labor Description / Comment	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual		
Comment # Material / Labor Description / Comment			Estimated		Qty	Actual		
 Comment # Material / Labor Description / Comment 1 Health and Safety CO monitor 	Each	1	Estimated		Qty	Actual		
# Material / Labor Description / Comment Health and Safety CO monitor Labor	Each	1	Estimated		Qty	Actual		
# Material / Labor Description / Comment Health and Safety CO monitor Labor	Each Hour	1	Estimated			Actual		
# Material / Labor Description / Comment Health and Safety CO monitor Labor	Each Hour	1	Estimated Unit Cost			Actual Unit Cost		

Measure 5 Replace Return Filter (20 x 20) Comment Include 10 Extra Filters				Componen	ts	Inspecte				
				Estimated	•		Actual			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total		
1 Labor			1							
2 Heating Equipmen			1							
Other Detail						1				
] [
]	Sub Total:			
			Measur	e Sub Total:			Sub Total:			
Measure 6 Smo Comment	ke Detector is Needed		Components					Inspecte		
# Material / Labor	Description / Comment	Units	Qty	Estimated Unit Cost	Total	Otv	Actual Unit Cost	Total		
Health and Safety		Each	4 <i>iy</i>	Omit Cost	Total	Qty		Total		
2 Labor	Labor	Hour	1							
	Labor		·							
Other Detail										
			Measur	e Sub Total:			Sub Total:			
Field Notes:										
				nd Total:			nd Total:			